

Nama Inspector : Rendy Dewantara
 No. Telp : 082297507069
 Tanggal Inspeksi : 03 Agustus 2025
 Jam Inspeksi : 10.45
 Lokasi Inspeksi : WTC Mangga 2, Ancol

Nama Customer : Bu Alex
 No. Telp : 08180000000
 Jenis & Tahun Kendaraan : Lexus RX300 2021
 Plat Nopol : B 0000 XXX
 Jarak Tempuk KM Mobil : 15.362

AUTORF

CAR INSPECTOR

TABRAK	BANJIR
TIDAK	TIDAK

KONDISI
GOOD

O : Normal X : Rusak Berat
 Δ : Rusak Ringan

EKSTERIOR DAN BODY

No	ITEM	KONDISI	CATATAN
BAGIAN UTAMA BODY			
1	Bumper Depan	O	
2	Kap Mesin	O	
3	Fender Depan Kanan	O	
4	Pintu Depan Kanan	O	
5	Pintu Belakang Kanan	O	
6	Fender Belakang Kanan	O	
7	Atap	O	
8	Fender Depan Kiri	O	
9	Pintu Depan Kiri	O	
10	Pintu Belakang Kiri	O	
11	Fender Belakang Kiri	O	
12	Pintu Bagasi dan Spoiler Belakang	O	
13	Bumper Belakang	O	
LAMPU & SISTEM PENCAHAYAAN			
14	Lampu Depan Kanan	O	
15	Lampu Depan Kiri	O	
16	Foglamp dan DRL Depan Kanan	O	
17	Foglamp dan DRL Depan Kiri	O	
18	Lampu Belakang Kanan	O	
19	Lampu Belakang Kiri	O	
20	Lampu Rem/Stop Lamp Belakang	O	
21	Lampu Sein Depan Kanan Kiri	O	
22	Lampu Sein Belakang Kanan Kiri	O	
23	Lampu Hazard	O	
24	Lampu Plat Nomor Depan & Belakang	O	
KACA, SPION & ACCESSORIES			
25	Kaca Keseluruhan	O	
26	Wiper Depan & Belakang	O	
27	Spion Kanan & Kiri	O	
28	Handle Semua Pintu	O	
29	Antena / Shark Fin	O	
30	Roof Rail / Rak Atap (jika ada)	O	
31	Logo / Emblem Keseluruhan	O	
32	Side Body Molding (jika ada)	O	
33	Talang Air (keseluruhan)	O	
34	Dudukan Kaki / Foot Step Kanan & Kiri	O	
35	Pelindung Kolong / Spakbor Dalam	O	
36	Sensor Parkir & Kamera Mundur	O	
37	Dop Roda (Semua Ban)	O	
38	Cover Ban Serep (Jika ada)	O	
39	Cover Tangki BBM	O	

RANGKA

No	ITEM	KONDISI	CATATAN
40	Bull Head Atas	O	
41	Bull Head Tengah	O	
42	Bull Head Bawah	O	
43	Strut Kanan	O	
44	Strut Kiri	O	
45	Upron Kanan	O	
46	Upron Kiri	O	
47	Pilar Pintu Depan Kanan & Kiri	O	
48	Pilar Pintu Belakang Kanan & Kiri	O	
49	Pilar Bagasi	O	

INTERIOR DAN FUNGSI FITUR

No	ITEM	KONDISI	CATATAN
DASHBOARD & PANEL KONTROL			
50	Dashboard (retak, goresan)	O	
51	Headunit (fungsi tombol, suara, display)	O	
52	Panel Instrumen (fungsi tombol, lampu indikator)	O	
53	Steer (fungsi tombol, tekstur, klakson)	O	
54	Airbag (retak, indikator menyala/tidak)	O	
55	Tombol Start/Stop Engine (jika tersedia)	O	
KENYAMANAN & KONTROL KABIN			
56	Doortrim Keseluruhan (retak, goresan)	O	
57	Door Locks/Central Lock	O	
58	Power Windows Semua Pintu	O	
59	Electric Retract Spion (pengaturan arah cermin)	O	
60	AC & Blower (Suhu, Fungsi Tombol)	O	
61	Plafon (Noda, Kendor, Sobek)	O	
62	Sunroof / Moonroof (Fungsi, Bocor)	O	
63	Jok (Sobek, Kotor, Pengaturan maju-mundur & recline)	O	
64	Sabuk Pengaman (Fungsi Semua titik)	O	
65	Karpet	O	
66	Console Tengah & Tempat Penyimpanan	O	
67	Lampu Kabin	O	
PENGENDALIAN BERKENDARA			
68	Pedal Gas, Rem, dan Kopling (cek respons & aus)	O	
69	Tuas Transmisi (gerak halus, indikator posisi jelas)	O	
70	Tuas Rem Tangan (elektrik/manual—cek fungsionalitas)	O	
71	Cruise Control (kalau ada—aktif saat test jalan)	O	
72	Saklar Lampu & Wiper (berfungsi semua)	O	

MESIN DAN TRANSMISI

No	ITEM	KONDISI	CATATAN
MESIN & KELISTRIKAN			
73	Internal Mesin Buka tutup Oli (Sludge, Kerak)	O	
74	Oli Mesin Buka Dipstik (Warna, Level)	Δ	Oli sedikit menghitam.
75	Kebocoran Oli (tampak atas, bawah, sumping)	O	
76	Suara Mesin saat idle dan akselerasi	O	
77	Getaran mesin saat idle dan rpm agak tinggi	O	
78	Engine mounting (retak, lemah)	O	
79	Oli Power Steering jika non-EPS (warna, level)	O	
80	Starter (respon cepat/delay)	O	
81	Indikator Check Engine	O	
82	AKI (Cek tegangan > 12.5V)	X	AKI Lemah, tegangan 12.39V (SOH 43%, SOC 65%)
83	Alternator (Cet tegangan stabil > 13.5V)	O	Tegangan 13.87V
84	Fuse box (konslet)	O	
85	Kabel & Soket (Longgar, putus)	O	
86	Asap Knalpot (warna, basah oli)	O	
87	Kondisi pipa Knalpot (retak, bocor)	O	
SISTEM AC & PENDINGIN			
88	Suhu AC (STD <10°C)	Δ	Suhu 11.3°C, kondisi dingin namun di atas standard (standard dibawah 10°C).
89	Blower Keseluruhan (arah semburan, suara, kisi2 patah)	O	
90	Kompresor AC (suara ngorok, rembes oli)	O	
91	Radiator (coolant, kerak, kebocoran, coklat campur oli)	O	
92	Kipas raditor (pecah, berputar normal)	O	
TRANSMISI & REM			
93	Oli Transmisi Buka Dipstik (Warna Level)	O	
94	Perpindahan Transmisi (halus, lompat)	O	
95	Tuas Transmisi (indikator jelas)	O	
96	Minyak Rem (warna, level)	O	
PEMERIKSAAN DIAGNOSTIC OBD2 SCANNER ECU			
97	Hasil Scan pertama (cek error)	X	Ditemukan 13 kode error
98	Hasil Scan kedua (clear DTC, cek error)	O	Kode error tidak muncul kembali

No	ITEM	KONDISI	CATATAN
SISTEM PENGEMUDI, SUSPENSI DAN PENEREMAN			
99	Rack Steer/Power Steering (bunyi, bocor, respons)	O	
100	Tie Rod inner & outer (longgar, karet robek)	O	
101	Link Stabilizer (longgar, karet robek)	O	
102	Ball Joint main & upper (longgar, karet robek)	O	
103	Drive Shaft, CV Joint inner & outer (karet robek, bunyi)	O	
104	Bushing Suspensi (longgar, karet robek)	O	
105	Shockbreaker / Suspensi (bocor, ayunan)	O	
106	Support Shock (Aus, Karat)	O	
107	Kampas Rem & Disk Brake (ketebalan)	O	
108	Kaliper Rem (karat, kebocoran)	O	
109	Selang rem & jalur minyak rem (retak/bocor)	O	
110	Parking Brake	O	
111	Kondisi Kolong Mobil (karat, kebocoran, bekas las)	O	
BAN & VELG			
112	Tahun Ban & Ketebalan	Depan Kanan	O Tahun 2021, kondisi 80%
113		Depan Kiri	O Tahun 2021, kondisi 80%
114		Belakang Kanan	O Tahun 2021, kondisi 90%
115		Belakang Kiri	O Tahun 2021, kondisi 90%
116	Ban Cadangan		O
117	Velg (barek, peang)		O

No	ITEM	KONDISI	CATATAN
118	STNK	O	
119	BPKB	O	
120	Faktur	O	
121	Surat Pelepasan Hak (SPH)	O	Milik pribadi
122	Cek legalitas Online	X	Sudah diblokir. Wajib balik nama.
123	Kunci Cadangan	O	
124	Buku Service	O	
125	Buku Manual	O	
126	Kunci-Kunci/Tools	O	
127	Dongkrak	O	

[illegible]

FOTO-FOTO TEMUAN

1. Oli mesin sedikit berwarna hitam



2. AKI lemah



3. Kondisi dingin namun di atas standard (STD dibawah 10°C).



4. Nomor Polisi sudah diblokir

Kendaraan ke-	001
Merek	LEXUS
Model	JEEP S.C.HDTP
Tipe	RX 300 F-SPORT 4X2AT.
Tahun Buat	2021
Warna	HITAM METALIK
BBM	BENSIN
Masa Pajak	15/07/2026
Masa STNK	15/07/2026
Nilai Jual	Rp. 1.073.000.000

PNBP Cetak STNK	Rp. 0
PNBP Plat (TNKB)	Rp. 0
PNBP NRKB Pilihan	Rp. 0
Pajak Kendaraan	Rp. 0
Denda Pajak	Rp. 0
SWDKLLJ	Rp. 0
Denda SWDKLLJ	Rp. 0
Total	Rp. 0
Keterangan	NOPOL BLOKIR JUAL
	KUNJUNGI SAMSAT

5. Hasil Scanning ECU pertama

All System Diagnostic Report	
The Report is created by THINKCAR	
Vehicle Information	
SN:9TFD20403808 Make:Toyota/Lexus Model:RX300 Year:2021 VIN:JTJZAMCA2M2111138 Mileage:9546 Miles Test Time:08/03/2025 11:25:55	
Inspection Result	
ABS (Brake Control)/EPB (Electrical Parking Brake) 1 problems exist 1.C14FE14 Steering Angle Sensor Supply Voltage Circuit Short to Ground or Open Confirmed TT (Tilt&Telescopic) 1 problems exist 1.B2624 Vehicles Speed History AC (Air Conditioning) 1 problems exist 1.B1449 Air Outlet Damper Control Servo Motor Circuit (Rear) History TPMS (Tire Pressure Monitoring System) 1 problems exist 1.C2123 Transmitter ID 3 not Received (Main) History CM (Combination Meter) 1 problems exist 1.B1326 Lost Communication with Clock Device (Local-CAN) History BCM (Body Control Module) 1 problems exist 1.B1249 Double Locking ECU Communication Stop History AFS (Adaptive Front-lighting System) 1 problems exist 1.B2414 Steering Position Sensor History ES (Entry&Start) 2 problems exist	

1.U0142 Lost Communication With Body Control Module 'B' History 2.U0155 Lost Communication With Instrument Panel Cluster (IPC) Control Module History PSC (Power Source Control) 1 problems exist 1.U0140 Lost Communication With Body Control Module History NS (Navigation System) 2 problems exist 1.B1326 Lost Communication with Clock Device (Local-CAN) History 2.B1323 Lost Communication with Haptic Device History IPA (Intuitive Parking Assist System)/ICS (Intelligent Clearance Sonar)/CS 1.C1AED Rear Sensor Communication Circuit History The following systems are OK: 1.ECM (Engine Control Module) 2.RCC (Radar Cruise) 1 3.TCM (Transmission Control Module) 4.EMPS (Electronic Motor Power Steering) 5.SRS (Supplemental Inflatable Restraint System) 6.AS (Air Suspension) 7.BD (Back Door) 8.SR (Sliding Roof) 9.DS (Driver Seat) 10.SS (Stop and Start) 11.CGW (Central Gateway) 12.DDM (Driver Door Motor) 13.PDM (Passenger Door Motor) 14.RLDM (Rear Left Door Motor) 15.RRDM (Rear Right Door Motor) 16.MSW (Master Switch)	17.SS (Sliding Sunshade) 18.MIR (Mirror) L 19.MIR (Mirror) R 20.RHS (Rain and/or Humidity Sensor) 21.WIP (Wiper) 22.SC (Starting Control) 23.CMCCM (Circumference Monitoring Camera Control Module) 24.BSM (Blind Spot Monitor) Master 25.BSM (Blind Spot Monitor) Slave 26.HUD (Head Up Display)
--	--

All System Diagnostic Report

The Report is created by **THINKCAR**

Vehicle Information

SN:9TFD20403808
Make:Toyota/Lexus
Model:RX300
Year:2021
VIN:JTJZAMCA2M2111138
Mileage:9546 Miles
Test Time:08/03/2025 11:27:25



Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.RCC (Radar Cruise) 1
- 3.TCM (Transmission Control Module)
- 4.ABS (Brake Control)/EPB (Electrical Parking Brake)
- 5.EMPS (Electronic Motor Power Steering)
- 6.TT (Tilt&Telescopic)
- 7.SRS (Supplemental Inflatable Restraint System)
- 8.AC (Air Conditioning)
- 9.AS (Air Suspension)
- 10.TPMS (Tire Pressure Monitoring System)
- 11.CM (Combination Meter)
- 12.BCM (Body Control Module)
- 13.AFS (Adaptive Front-lighting System)
- 14.BD (Back Door)
- 15.SR (Sliding Roof)
- 16.DS (Driver Seat)
- 17.ES (Entry&Start)
- 18.SS (Stop and Start)
- 19.CGW (Central Gateway)
- 20.DDM (Driver Door Motor)
- 21.PDM (Passenger Door Motor)
- 22.RLDM (Rear Left Door Motor)

- 23.RRDM (Rear Right Door Motor)
- 24.MSW (Master Switch)
- 25.SS (Sliding Sunshade)
- 26.MIR (Mirror) L
- 27.MIR (Mirror) R
- 28.RHS (Rain and/or Humidity Sensor)
- 29.WIP (Wiper)
- 30.PSC (Power Source Control)
- 31.SC (Starting Control)
- 32.NS (Navigation System)
- 33.CMCCM (Circumference Monitoring Camera Control Module)
- 34.BSM (Blind Spot Monitor) Master
- 35.BSM (Blind Spot Monitor) Slave
- 36.HUD (Head Up Display)
- 37.IPA (Intuitive Parking Assist System)/ICS (Intelligent Clearance Sonar)/CS (Clearance Sonar)